



Fig. 1. A schematic drawing of a disk drive and some of the components

PRIOR ART



PRIOR ART

Fig. 2. Cross-track motion causing track mis-registration error (TMR)






FIG. 3B.




FIG. 4A




FIG. 5




FIG. GA

SECTION AA

FIG. 6B

FIG. 6C





FIG. 7A








FIG. 7C








FIG. 9A




FIG. 9B